test report

Supplier：	Zhejiang	Po No.：	20KD88182001
CUST No.:	NIK18071	Inspection unit：	验货房
Factory Contact ：	20KD88182001	Inspection Date ：	11/18/20

inspection item	TCF	Measured Data			Result
Length	Length：+0.3mm/-0mm	1830,02	1830,06	1830,08	√
Width	Width：+0.12mm/-0mm	229,01	229,05	229,08	√
Thickness	+0.2mm-0.15mm	5,57	5,56	5,57	√
Gloss	±1.5°	5,5	5,6	5,1	√
Shrinkage rate	ESPC≤0.08%	0,04%			√
expansion rate	≤0.15%	0,09%			√
Curling after exposure to heat:	ESPC≤1mm	0,60			√
opengings	≤0.1mm	0,10			√
Height difference	≤0.15mm	0,10			√
Batch No.、Click type	Accoring to the order requirments	OK			√
Label	1.The label is not re-attached, floating, or skewed. 2. the Lable is same as the order requirments	OK			√
Carton	1.The carton shall not be damaged ,worn ,dirty or fade 2.The carton should be put in order. 3.Confirm if the carton is same as the order requirments	OK			√
Pallet	The pallet surface shoule be smooth and flat,pallet blocks shall not be damaged,pallet size should be same to the order	OK			√
Appearance	Inspection Level：AQL LevelII 2.5&4.0	Impurity material inside the surface：1pc			√

验货照片









检验结果：√合格 □待定 □不合格　　检验员：张恒　　审核：罗泽敏　　报告填写日期：2020-11-18

test report

Supplier：	Zhejiang Co.,Ltd	Po No.：	20KD88182001
CUST No.:	NIK18201	Inspection unit：	Zhejiang
Factory Contact ：	20KD88182001	Inspection Date ：	11/18/20

inspection item	TCF	Measured Data			Result
Length	Length：+0.3mm/-0mm	1830,02	1830,06	1830,08	√
Width	Width：+0.12mm/-0mm	229,02	229,06	229,05	√
Thickness	+0.2mm-0.15mm	5,55	5,60	5,58	√
Gloss	±1.5°	5,6	5,4	5,4	√
Shrinkage rate	ESPC≤0.08%	0,04%			√
expansion rate	≤0.15%	0,11%			√
Curling after exposure to heat:	ESPC≤1mm	0,60			√
opengings	≤0.1mm	0,10			√
Height difference	≤0.15mm	0,10			√
Batch No.、Click type	Accoring to the order requirments	OK			√
Label	1.The label is not re-attached, floating, or skewed. 2. the Lable is same as the order requirments	OK			√
Carton	1.The carton shall not be damaged ,worn ,dirty or fade 2.The carton should be put in order. 3.Confirm if the carton is same as the order requirments	OK			√
Pallet	The pallet surface shoule be smooth and flat,pallet blocks shall not be damaged,pallet size should be same to the order	OK			√
Appearance	Inspection Level：AQL LevelII 2.5&4.0	Dirty mark on the surface：1pc			√

验货照片





检验结果：√合格 □待定 □不合格　　检验员：张恒　　审核：罗泽敏　　报告填写日期：2020-11-18

test report

Supplier：	Zhejiang Co.,Ltd	Po No.：	20KD88182001
CUST No.:	NIK15143	Inspection unit：	Zhejiang
Factory Contact ：	Lucky Mi	Inspection Date ：	12/18/20

inspection item	TCF	Measured Data			Result
Length	Length：+0.3mm/-0mm	1511,00	1511,00	1511,00	√
Width	Width：+0.12mm/-0mm	229,00	229,00	229,00	√
Thickness	+0.2mm-0.15mm	5,56	5,59	5,57	√
Gloss	±1.5°	5,4	5,7	6,1	√
Shrinkage rate	ESPC≤0.08%	0,03%			√
expansion rate	≤0.15%	0,08%			√
Curling after exposure to heat:	ESPC≤1mm	0,40			√
opengings	≤0.1mm	0,10			√
Height difference	≤0.15mm	0,10			√
Batch No.、Click type	Accoring to the order requirments	OK			√
Label	1.The label is not re-attached, floating, or skewed. 2. the Lable is same as the order requirments	OK			√
Carton	1.The carton shall not be damaged ,worn ,dirty or fade 2.The carton should be put in order. 3.Confirm if the carton is same as the order requirments	OK			√
Pallet	The pallet surface shoule be smooth and flat,pallet blocks shall not be damaged,pallet size should be same to the order	OK			√
Appearance	Inspection Level：AQL LevelII 2.5&4.0	Impurity material inside the surface： 1pc			√

Inspection picture



检验结果：√合格 □待定 □不合格　　检验员：罗顺友　　审核：彭伟　　报告填写日期：2020-12-18